



info@massmetal.com.ar

 +54 9 11 6675 5548

Catálogo

HEBILLAS

Hebillas con pitón



5482
Pase 8mm



1322
Pase 8mm



--



411
Pase 12mm



3958
Pase 15mm



2552
Pase 8mm



--



98
Pase 8mm



7731
Pase 15mm



7732
Pase 10mm



2096
Pase 40mm



2094
Pase 40mm



1734
Pase 50mm



1609
Pase 50mm



7309
Pase 30mm



7232
Pase 35mm



4913
Pase 35mm



4912
Pase 35mm



4911
Pase 40mm




1805
Pase 32mm



5236
Pase 25mm



1661
Pase 33mm



4709
Pase 40mm



4702
Pase 35mm



6614
Pase 25mm



3429
Pase 25mm



2966
Pase 45mm



651
Pase 40mm



5244
Pase 20mm



4710
Pase 25mm



4908
Pase 40mm



4909
Pase 40mm



4910
Pase 53mm



4917
Pase 40mm



4916
Pase 60mm



5589
Pase 25mm



3845
Pase 40mm



3754
Pase 75mm

Hebillas con perno



4773
Pase 35mm



4918
Pase 40mm



4739
Pase 50mm



5016
Pase 30mm



2337
Pase 30mm



2953
Pase 40mm



4914
Pase 40mm



4915
Pase 34mm



4691/92/93
--



4772
Pase 33mm



4774
Pase 35mm



4685
Pase 30mm



2882
Pase 40mm



3611
Pase 30mm



4819
Pase 30mm



4775
Pase 30mm



9216
Pase 40mm



2634
--



2620
Pase 30mm



3661
Pase 30mm



3612
Pase 40m



4531
Pase 30mm



3851
Pase 40mm



1837
Pase 25mm



997
Pase 20mm



2601
Pase 30mm



3386
Pase 30mm



3595
Pase 30mm

Detalle de Aplicación



Pasador móvil



Pasador fijo



Pasador remachado

Hebillas de encastre



5456
Pase 15mm - 27x20mm



1508
Para coser - 30x25mm



1533
Para coser - 48x25mm



643
Para coser - 27x15mm



1536
Pase 15mm - 48x16mm



384
Para coser - 20x15mm



1784
Para coser - 45x22mm



1248
Para coser - 38x16mm



1023
Para Coser - 28x15mm



1643
Con remache - 30x32mm



5225/26
Pase 30mm
85x45mm



5641
Pase 24mm
50x30mm



5068/69
Para coser
70x35mm



5026/27
Para coser
95x15mm



2933
Pase 90mm
45x95mm



3024
Pase 50mm
135x80mm



1683
Pase 35mm
70x50mm



2925
Pase 50mm
80x65mm




3373
Pase 38mm
80x50mm



3855
Pase 55mm
100x60mm



4115
Pase 60mm
65x65mm



3753
Pase 50mm
70x70mm



5074/75
Para Coser
65x30mm



5070/71
Para coser
50x26mm

TRABAS PARA PULSERAS DE CUERO



7617
Pase 20mm - 34x24mm



7166
Pase 10mm - 40x15mm



6412
Pase 11mm - 35x14mm



6942
Pase 11mm - 40x13mm

TRABAS PARA PULSERAS DE CUERO



6934
Pase 5mm - 30x8mm



6938
Pase 6mm - 52x10mm



6944
Pase 6mm - 27x7mm



6935
Pase 7mm - 30x10mm

Detalle de Aplicación



Hebillas de encastre para pulsera